

Extras din istoricul vehiculului

Report ID:	3227827525
Data achiziției raportului:	21. 05. 2024 17:29:23
Valabil până la:	20. 06. 2024 17:29:23

Acest raport a fost creat în urma solicitării serviciului Car History operat de Cebia spol. s r.o. conform Termenilor și Condițiilor Generale valabile de utilizare a serviciului Car History. Utilizatorul are dreptul de utilizare a informațiilor furnizate în întregime numai pentru propriile necesități. Diseminarea sau modificarea ulterioară a acestora fără acordul operatorului este interzisă.

1. Datele de bază ale vehiculului



VIN
WVGZZA1ZJV020516


Marca
VOLKSWAGEN

Model
T-ROC

Data fabricației
14. 12. 2017

2. Verificare kilometraj

Prezentarea generală a datelor odometruului vehiculului conține valori obținute din sistemele de informații disponibile ale partenerilor de colaborare. În funcție de evoluția stării odometruului în timp, puteți evalua dacă există sau nu o suspiciune de modificare a datelor odometruului.



3. Prezentare generală a istoriei

Data	Starea odometrului		Țara	Descriere
2017	decembrie	0 km		Vehicul fabricat
	Data fabricației: Vechimea vehiculului: Culoarea mașinii: Fabricat pentru piața: Postul de conducere: 14. 12. 2017 6 ani 5 luni Cod B8R România partea stângă			
2018	ianuarie		 România	Înregistrare RAR
2019	ianuarie			Fotodocumentare
2021	martie	65 500 km	 România	Inspekția tehnică
	martie			Fotodocumentare
	iulie	70 500 km	 România	Înregistrare RAR
2023	martie	110 000 km	 România	Inspekția tehnică

4. Verificarea daunelor

Nu s-au găsit înregistrări cu privire la daune

Nu au fost găsite înregistrări cu privire la daune în bazele de date de vehicule avariate din peste 32 țări, numărând 200 de milioane de înregistrări de daune.

Cu toate acestea, vă recomandăm inspekția atentă a vehiculului, preferabil cu ajutorul unui mecanic calificat sau la un service la alegere. O astfel de inspekție poate detecta cu precizie sau exclude daunele anterioare.

Avertisment: Serviciul Car History poate să nu includă informații despre toate daunele vehiculului, unele daune nu sunt raportate companiilor de asigurări sau nu sunt disponibile în cazul inspekției online.

5. Înregistrări de service

Nu au fost găsite înregistrări în bazele de date ale serviciului. Solicitați o declarație din cartea de service (de preferință din cartea electronică de service) a vehiculului. Autenticitatea operațiunilor de service poate fi verificată direct la atelierul de reparații auto, unde au fost efectuate conform cărții de service.

6. Controlul furturilor

Nu este înregistrat drept furat

în bazele de date disponibile actualmente

Datele comunicate au caracter informativ. Cebia nu este responsabilă de daunele suferite în urma utilizării datelor distribuite.

Sursa	La zi: 21. 05. 2024
 Cehia - Poliție	NF - nu este înregistrat drept furat
 Ungaria - Poliție	NF - nu este înregistrat drept furat
 România - Poliție	NF - nu este înregistrat drept furat
 Slovenia - Poliție	NF - nu este înregistrat drept furat
 Ucraina - Poliție	NF - nu este înregistrat drept furat
 Canada - Poliție	NF - nu este înregistrat drept furat
 Suedia - Baza de date a companiilor de asigurare	NF - nu este înregistrat drept furat
 UE - Bazele de date private*	NF - nu este înregistrat drept furat

* Bazele de date private de obicei permit oricui să introducă informații despre furt.

7. Verificare utilizare

Vehiculul nu a fost exploatat ca taxi în Republica Cehă

În bazele de date disponibile s-a constatat că vehiculul nu a fost și nu este folosit în prezent ca taxi.

8. Verificarea finanțării

Finanțarea nu a fost găsită

Rezultatul solicitării constă în verificarea dacă vehiculul nu este obiectul finanțării (sub formă de leasing sau credit), garanții și împrumut de la companiile enumerate. Datele provin din sistemele informatice ale companiilor individuale.

Țara	La zi: 21. 05. 2024
Cehia	NF - nu este înregistrat

9. Lista elementelor echipamentelor conform producătorului

Următorul tabel include informații detaliate despre echipamentul vehiculului: informațiile despre parametri de bază ai vehiculului selectat, echipamentele standard și eventual cele suplimentare la punerea în funcțiune a vehiculului, adică echipamentul din producție.

Identificarea vehiculului	
Marca	Volkswagen
Numele modelului	T-Roc
Denumirea modelului	T-Roc 4Motion BlueMotion Technology
Data fabricației	14.12.2017
Cod de culoare	B8R
Codul culorii acoperișului	B8R
Echipament	Vybavení (Black oak ceramique)
Codul cutiei de viteze	SWT
Codul motorului	DFFA
Capacitate motor ccm	1968
Capacitatea motorului(l)	2,00
Performanță(kW)	110
Numărul de cilindri	4
ISO numele țării	Romania
Transmisie	AUT
Cod de control	LHD
Tipul de vânzare	A1136T

Lista elementelor echipamentului vehiculului	
"Charism"	Driving profile selection and conventional shock absorber
"Multimedia", video/DVD/notebook connection	Mirror Link
Activated carbon canister	Without activated charcoal canister with SCR
Additional child seat anchors	Child seat anchor for child seat system ISOFIX
Additional tires (winter tires)	Without additional tires
Additional warning lights	Additional reflectors (door area)
Air bag	Driver's and front passenger air bag with front passenger air bag deactivation

Lista elementelor echipamentului vehiculului

Alternative drive module	Without alternative drive module
Antennas	Antenna for FM reception only, diversity
Anti-theft protection system	Electronic vehicle immobilization device
Audio-response system/voice control	Without voice control
Auxiliary heating	Without auxiliary/parking heater
Backrest release	Backrest release for right front seat
Base engine	4-cylinder diesel engine 2.0 L unit 04L.B
Batteries	Battery 420 A (70 Ah)
Battery/alternator capacity	Standard battery/alternator capacity
Body measures	Without special body measures
Body style	Hatchback
Brake pad wear indicator	Brake pad wear indicator
Brake type, front	Disc brakes, front
Brake type, rear	Disc brakes, rear
Braking systems	Electronic stabilization program (ESP)
Breakaway interior mirror	Breakaway interior rear view mirror, automatically dimming
Bumper	Standard bumpers
Call feature	Without emergency call control unit
Camera systems/accident sensors	Without camera systems/accident sensors
Camera/distance sensor	Camera and/or distance sensor (driver assistance system)
Carrier frequency for radio remote control	Carrier frequency 433.92 MHz-434.42 Mhz
CD ROM/DVD/SD card	Without CD/DVD for navigation
Center armrest	Front center armrest
Climatic zones	Standard climatic zones
Compass/traffic sign display	Without traffic signs recognition
Component part sets with country-specific design requirements	Component parts set without country-specific design requirement
Components with special surface appearance	Body-colored exterior mirror housings and various add-on parts
Cruise control	Adaptive Cruise Control (w/ "Follow-to-Stop") and Speed Limiter
Customized installation	Without customized installation

Lista elementelor echipamentului vehiculului

Door and lid locking system	Radio remote controlled central locking operated from inside without safe lock
Door and side trim panels	Door and side trim panel
Doors	4 doors
Drawers under front seats	Drawer under right front seat
Drive layout	Four wheel drive
Driving on the left/on the right	Driving on the right
ECO function for driving profiles and drive select	ECO function
Electric interface for external use	Electric interface for external use, 2 x USB
Emission standard	Emission standard EU6 plus
Engine cooling system	Not hot country
Engine specifications	4-cylinder turbo diesel engine 2.0 l/110 kW (4V) TDI common rail; b.e. T37/TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I
Equipment levels	Comfort equipment
Exhaust tailpipe	Rear side exhaust tailpipe
Extended safety system	Without extended safety system
Exterior mirror setting	Exterior mirrors: electrically adjustable, separately heated
First aid kit / warning triangle	Warning triangle
Floor mats	Front and rear floor mats
Folding table	W/o folding table on front seat backrest
Front Assist	Front Assist incl. city automatic emergency braking for ACC high
Front fog light/additional headlight	Front fog lamp and cornering lamp
Front seats	Comfort front seats
Front stabilizer	Front stabilizer
Front underbody guard	Without additional front underbody guard
Fuel quantity for initial filling	Initial standard fuel filling
Fuel systems	Fuel system for diesel engine
Gearshift knob/handle	Leather gearshift knob/handle
General operating permit, alterations	Operating permit, alteration
Generators	Alternator 140 A
Headlight	LED headlamps

Lista elementelor echipamentului vehiculului

Headlight activation	Separate daytime running lights with low beam assistant and "Coming Home" feature
Headlight washer system	Without headlight washer system
Headlight-range adjustment	Automatic headlight-range adjustment dynamic (self-adjusting while driving)
Headrests	Front headrests
Heat accumulator system/additional heater	Electric auxiliary air heater
Heated washer nozzles	Heated washer nozzles, front
Heating and air conditioning system	Climatronic with impact pressure control free of cfc
Hill hold control	Hill hold control / hill descent control
Horns	Two-tone horn
Hybrid drive	Without electric motor (hybrid)
Charging cable	Without charging cable
Chrome work package	Chrome work package
Identification plates	Special identification plate for EC for M1 passenger vehicle
Inserts	Decorative inserts
Installation differentiation for vehicle components	Installation differentiation for transmission "DQ381" -- vehicle components --
Instrument inserts	Instrument insert, km/h speedometer
Interior light in foot area	Without interior light in footwell
Left exterior mirror	Left exterior mirror: aspherical
Light assistance system	Without light assistant
Light package (lighting)	Without add. lights (interior lighting)
Lock operation for tailgate/trunk lid	Tailgate/trunk lid unlocking from outside
Lockable wheel bolts	Wheel bolts with anti-theft protection (unlockable)
Lumbar support	Manually adjustable lumbar support in front seats
Manufacturing sequence differentiation	Standard manufacturing sequence
Mass damper for steering wheels	Mass damper for steering wheel, 36 Hz
Molding roof liner	Unsplit molding roof liner
Moldings	Bright moldings
Multi-function display/trip computer	Multi-function display/on-board computer "Medium"
Nameplate set	Nameplate set in base trim

Lista elementelor echipamentului vehiculului	
Navigation device	Without navigation device
Online services	Without online service
Operating voltage	Operating voltage 12V
Outer rear seat belts	3-point seat belts, outer rear with ECE label
Outside sound measures	Standard outside sound
Owner's manuals	Information kit in Romanian
Paint coating	Standard paint coating
Paint preservative/transit coating	Transport protection film (minimum protection) with additional transport protection measures
Park distance control	Park distance control, front and rear
Parking brake	Parking brake
Partition	Without partition
Pedal cluster	Standard pedal cluster
Pedestrian protection	Extended and proactive pedestrian protection
Platform module floor pan, rear	Rear floor panel module, type 7
Preparation for two-way radio installation	Without preparation for two-way radio installation
Radios	.
Reading light	Reading light front
Rear axle	4-link rear suspension
Rear cargo area	Variable cargo area concept
Rear fog light	Rear fog light
Rear headrests	Three rear headrests
Rear seats	Rear seat bench unsplit, backrest split folding with center armrest
Rear stabilizer	Rear stabilizer
Rear window wiper and washer system	Rear window wiper and washer system with intermittent control
Refrigerant	Refrigerant R1234yf
Refrigerator	Without refrigerator/glove compartment cooling system
Regional code for radio	Regional code " ECE " for radio
Rest Assist	Without Rest Assist
Restraint systems, front	3-point seat belts with tensioner and height adjustment, front
Right exterior mirror	Right exterior mirror: convex

Lista elementelor echipamentului vehiculului

Roof insert/convertible top	Without roof insert (standard roof)
Roof rails/roof load rack	Black roof rails
Seat adjustment	Manual height adjustment for front seats
Seat belt check	Seat belt reminder, electric contact in the buckle, advanced safety equipment
Seat covering	Fabric seat covering
Seat heater	Seat heater for front seats separately controlled
Service indicator	Service indicator 30,000 km or 2 year (variable)
Service interval prolongation	Service interval prolongation
Shock absorption, chassis, front	Front shock absorption
Shock absorption, chassis, rear	Rear shock absorption, chassis with increased ride height
Side air bag	Side air bag front with curtain air bag
Side and rear windows	Side windows in heat-insulating glass, from B-pillar and rear window dark tinted
Side assist/lane departure warning	Lane departure warning
Smoking/non-smoking package	Smoking package, ashtray front
Socket	12-volt socket(s)
Spare wheel/breakdown set	Space-saving spare wheel
Speaker installation	6 speakers (passive)
Special editions	No special edition
Special labels/plates	Labels/plates in Romanian and English
Start/stop system/regenerative braking	Start/stop system with regenerative braking
Steering	Speed-related variable steering assist (Servotronic)
Steering system arrangement	Left-hand drive vehicle
Steering wheels	Leather multi-function steering wheel
Subsequent guarantee	Without subsequent warranty
Sun visors	Sun visors with mirror, on front passenger side with airbag label on sun visor and B-pillar
Taillight assemblies	LED taillamp assembly
Telephone/telematics	Mobile phone preparation
Tire categorization	Category 2
Tire pressure warning light	Tire pressure warning light
Tires	Tires 215/55 R17 94V optimized rolling resistance

Lista elementelor echipamentului vehiculului	
Tool kit and jack	Tool kit and jack
Trailer hitch	Without trailer hitch
Transmission specifications	7-speed automatic transmission for four-wheel drive vehicle
TV reception/digital radio reception	W/o TV reception/digital radio reception
Type approval countries/countries with special requirements	Type approval Romania
Upgrading measures	Vehicles w/o special upgrade measures
Vehicle class differentiation units/platform components	Vehicle class differentiation 2GA-
Vehicle inlet	Without vehicle inlet
Vehicle specifications	No special purpose vehicle, standard equipment
Versions	Basic equipment variant
Washer fluid level indicator	Washer fluid level indicator
Weight category front axle	Suspension range 05 installation control only, no requirement forecast
Weight category rear axle	Weight range 3 installation control only, no requirement forecast
Wheel covers	Covers for alloy wheels
Wheelbases	Wheelbase
Wheels	Alloy wheels 7J x 17
Window regulator	Power windows with comfort operation and circuit breaker
Windshield glass type	Windshield in heat-insulating glass
Windshield wiper intermittent control/ light/rain sensor	Windshield wiper intermittent control with light/rain sensor
Altele	Adaptive Cruise Control ACC and ambient traffic monitoring "Front Assist" with veh.stop feature a.City Emergency Brake
Altele	Alloy wheels 8J x 18" BRAGA anthracite, bright machining + tires with super-low rolling resistance
Altele	All-weather tires "Oslo" - 4 alloy wheels 6.5J x 16 - all-weather tires 205/55 R16
Altele	Audi Sport cast aluminium alloy wheels, 5-spoke blade design, size 9J x 21 with 265/30 R 21 tyres
Altele	Forged aluminium alloy wheels, 7-Y-spokedesign, 8.5Jx17, with 245/45 R 17 tyres,with run-flat properties
Altele	Leather-wrapped multi-function steering wheel (3-spoke) with decorative matte chrome inserts
Altele	Leather-wrapped multi-function steering wheel w/ controls for gear shift, multi-function display, radio, and telephone
Altele	Multi-function steering wheel, hand brake and gearshift knob in leather, instrument cluster "High"
Altele	seat package 1 (3rd row): 1 separate seat, right, with longit. adjustment, textile floor mats for 3rd row of seats

Lista elementelor echipamentului vehiculului

Altele	special package "Dynamic" (with alloy wheels "Style")
Altele	Winter package I: heated front seats, heated exterior mirrors, heated washer nozzles and heated headlamp washer syst.

10. Notificări de rechemare

Nu au fost găsite notificări de rechemare care

vizează mașina inspectată

Notificările de rechemare se anunță de către producătorul vehiculului în mod obligatoriu prin lege în cazul în care vehiculul prezintă un defect de fabricație care pune în pericol sănătatea, siguranța sau mediul înconjurător. În cadrul notificării de rechemare, defecțiunea din serviciul autorizat este remediată gratuit. Datele sunt furnizate de portalul [Car-recalls.eu](https://car-recalls.eu) cu ajutorul sistemului RAPEX.

11. Verificarea culorii vehiculului

Verificați dacă culoarea actuală a vehiculului se potrivește cu culoarea declarată de producător. Dacă culoarea este diferită, vehiculul poate fi revopsit, dar și prăbușit sau furat.

Culoarea mașinii

Culoarea conform producătorului vehiculului	Cod B8R
---	---------

12. Verificarea securității vehiculului

Rezultatul inspecției constă în informații dacă vehiculul inspectat este securizat sub forma marcajelor pe sticlă și înregistrat în Sistemul OCIS. Dacă da, vă vom informa în privința codului marcat și a datei de înregistrare.

Informații despre efectuarea marcajului geamurilor	21. 05. 2024
--	--------------

Marcajul geamurilor	NU
---------------------	----



13. Fotografii și anunțuri publicitare

În cazul în care vehiculul a fost anunțat sau inspectat în trecut, vom afișa informații și documente foto.

Record 1/4	Fotografii
------------	------------

Data plasării anunțului	20. 01. 2019
-------------------------	--------------







Record 2/4

Fotografii

Data plasării anunțului

20. 01. 2019









Record 3/4

Fotografii

Data plasării anunțului

18. 03. 2021





Record 4/4

Fotografii

Data plasării anunțului

18. 03. 2021



